## GOVERNMENT OF ANDHRA PRADESH <u>ABSTRACT</u>

Public Service – I&CAD Dept. – Allegations of irregularities in tender and substandard execution of work in RDS and Priyadarshini Jurala Project - Disciplinary proceedings initiated – warned – Orders – Issued.

# IRRIGATION & C.A.D. (Ser.VII.(V&E)A.1) DEPARTMENT

G.O.Rt.No. 291 Dated: 26-03-2011
Read the following:

- From the Director General (Vig. & Enft.) & E.O. Prl. Secy. to Govt., G.A.D. Vigilance Report No.23(920/V&E/E1/05), Dt. 02.03.2006
- 2. G.O.Rt.No.1244 I&CAD(Ser. VII(V&E)A1) Dept. dt.05-11-2007.
- 3. G.O.Rt.No.1245 I&CAD(Ser. VII(V&E)A1) Dept. dt.05-11-2007
- 4. G.O.Rt.No.1246 I&CAD(Ser. VII(V&E)A1) Dept. dt.05-11-2007
- 5. G.O.Rt.No.1250 I&CAD(Ser. VII(V&E)A1) Dept. dt.05-11-2007
- 6. G.O.Rt.No.1251 I&CAD(Ser. VII(V&E)A1) Dept. dt.05-11-2007
- 7. G.O.Rt.No.1252 I&CAD(Ser. VII(V&E)A1) Dept. dt.05-11-2007
- 8. G.O.Rt.No.1257 I&CAD(Ser. VII(V&E)A1) Dept. dt.05-11-2007
- 9. G.O.Rt.No.1260 I&CAD(Ser. VII(V&E)A1) Dept. dt.05-11-2007
- 10. G.O.Rt.No.1261 I&CAD(Ser. VII(V&E)A1) Dept. dt.05-11-2007
- 11. From Sri C. Venkataram Reddy EE WSSD Dt. 3-1-2008
- 12. From Sri G. Gopal, Dy.EE, AE, WSSD Dt. 03-01-2008
- 13. From Sri J, Anjanalu, AE, WSSD Dt. 3-1-2008
- 14. From Sri J. Sathyanand, SE, WSSD Dt. 23-01-2008
- 15. From Sri G. Ratnaiah, Dy.EE, WSSD Dt. 03-01-2008
- 16. From Sri P. Chandra Sekhar, AE, WSSD Dt. 03-01-2008
- 17. From Sri Syed Riyazuddin, AE, WSSD Dt. 03-01-2008
- 18. From Sri T.P. Bozorama, Dy.EE, WSSD Dt. 03-01-2008
- 19. From Sri K. Prahalda Reddy, Dy. EE, WSSD Dt. 03-01-2008.
- 20. Govt. Memo No. 8901/Ser.VII(V&E)A1/2006-9, Dt. 24-12-2011.
- 21. From Chief Engineer(Projects) Mahabubnagar Lr.No. DCE1/OT8/SO3/RDS/8901/06, Dt. 14-02-2011.

\*\*\*\*

### **ORDER:**

In the reference 1<sup>st</sup> read above, it was brought to the notice of the Government that allegations of irregularities in tender and substandard execution of work in RDS and Priyadarshini Jurala Project, Mahabubnagar Dist. and the following officers were found responsible for the lapses.

- 1. Sri C. Venkataram Reddy EE
- 2. Sri G. Gopal, Dy.EE, AE
- 3. Sri J, Anjanalu, AE
- 4. Sri J. Sathyanand, SE
- 5. Sri G. Ratnaiah, Dv.EE
- 6. Sri P. Chandra Sekhar, AE
- 7. Sri Syed Riyazuddin, AE
- 8. Sri T.P. Bazaranna, Dy.EE
- 9. Sri K. Prahalda Reddy, Dy. EE.
- 2. After examining the matter, it was decided to initiate departmental action on the individuals responsible for irregularities in tender and substandard execution of work in RDS and Priyadarshini Jurala Project, Mahabubnagar Dist Accordingly, in the reference 2<sup>nd</sup> to 10<sup>th</sup> read above, charges were framed against above engineers along with other Engineers inviting their written statements of defence.

- 3. In the reference 11<sup>th</sup> to 19<sup>th</sup> read above, all the above charged officers along with other charged officers have submitted their WSSDs along with copies of evidences in support of their claim with a request to drop further action against them.
- 4. After examination of the WSSDs of the individuals, it was provisionally decided to issue warning against the persons referred to at para (1) above, after obtaining a certificate to the effect that no cracks are formed in the lining works executed by the engineers against whom charges are proposed to be dropped. Accordingly in the reference 20<sup>th</sup> read above, the Chief Engineer(P), Mahaboobnagar was directed to furnish a certificate stating whether there are any structural cracks causing consequential damages to the functioning of canal in the following reaches and whether water is reaching tail end of RDS and Priyadarshini Jurala Project in respect of the packages 1. PRD 8, 2. PLD 7, 3. RL 6, 4. PRD 7 5. RL- 8, 6. RL- 9, 7. PLD 6, 8. RL-5 and 9. R.L. 7 for taking further action.
- 5. In the reference 21<sup>st</sup> read above, the Chief Engineer(Projects), Mahaboobnagar, has submitted that the Superintendent Engineer, PJP circle, Gadwal has reported that the CC Lining of packages mentioned in the Govt. Memo were inspected and observed that, no appreciable structural cracks were found and CC lining work is intact and good in appearance and the Canals are functioning and water is reaching the tail end area of Distributaries of PJP & RDS Canal.
- 6. Government., after taking into consideration of the report of the Chief Engineer(Projects), Mahaboobnagar, have decided to issue warning against Sri C. Venkataram Reddy EE and (8) others referred to at para (1) above in respect of the charges relating to irregularities in tender and substandard execution of work in RDS and Priyadarshini Jurala Project, Mahabubnagar Dist. Accordingly Sri C. Venkataram Reddy EE and (8) others referred to at para (1) above here by warned in respect of the charges relating to irregularities in tender and substandard execution of work in RDS and Priyadarshini Jurala Project, Mahabubnagar Dist.
- 7. The I&CAD(Ser.I) & (Ser.II) Department/Engineer-in-Chief (AW) , I&CAD Department, Hyderabad shall take necessary further action.

(BY ORDER AND IN THE NAME OF THE GOVERNOR ANDHRA PRADESH)

## SHAILENDRA KUMAR JOSHI PRINCIPAL SECRETARY TO GOVERNMENT

To

The Individuals through Engineer- in -Chief (Admn.Wing), I&CAD Department, Hyderabad.

The Engineer- in -Chief (Admn.Wing), I&CAD Department, Hyderabad.

The I&CAD (Ser.I) & (Ser.II) Department

#### Copy to:

The Chief Engineer(Projects), Mahaboobnagar The General Administration (V&E) Department. The Secretary to VC, APVC, Hyderabad. SC/SF

//FORWARDED : BY ORDER//

**SECTION OFFICER**